

VIN	WDD1714561A001234	Model series/model designation	203.052
Order number		License plate	

Full list of fault codes and events

9000	Control unit N80 (Steering column module) is defective.
9326	Component S40 (CC switch) is defective.
9327	Component S59 (Steering column adjustment switch) is defective.
9328	Component S59 (Steering column adjustment switch) is defective.
9329	Component S110s5 or S111s5 (pushbutton for fanfare horns) is defective.
9330	Component S111s1 (pushbutton + and -, setting specific functions and volume control) is defective.
9331	Component S111s3 (Accept/terminate phone call pushbutton) is defective.
9332	Component S110s1 (Scroll forward/back pushbutton) is defective.
9333	Component S110s3 (System select pushbutton) is defective.
9335	Component S93/2 (VCS switch) is defective.
9337	Component 'W 5.1' is defective.
9338	Component 'W 5.2' is defective.
9339	Component 'W 6.1' is defective.
9340	Component 'W 6.2' is defective.
9341	Component 'W 7.1' is defective.
9342	Component 'W 7.2' is defective.
9343	Component 'W 8.1' is defective.
9344	Component 'W 8.2' is defective.
9352	Steering angle sensor speed too high
9353	Steering angle sensor has overflow.
9357	Component S59/1s2 (Steering wheel heater switch) is defective.
9358	Component S4s4 (Windshield washer system switch) is defective.
9359	Component S4s2 (Headlamp flasher and high beam switch) is defective.
935C	Component S111/2 (Right steering wheel gear shifter) is defective.
935D	Component S110/2 (Left steering wheel gear shifter) is defective.
Event 9010	The supply voltage of component N80 (Steering column module) is too low (undervoltage).
Event 9011	The supply voltage of component N80 (Steering column module) is too high (overvoltage).
Event 9325	Multifunction steering wheel interface: short circuit of signal line $\Gamma \neg _$
Event 9345	Fault in CAN communication with control unit EZS.
Event 9346	Fault in CAN communication with control unit Instrument cluster.
Event 9347	Voltage value of control unit EZS not present.
Event 9348	Communication over engine CAN bus is faulty.
Event 9349	Communication over engine CAN bus is faulty.
Event 9350	Communication through the interior CAN bus is faulty.
Event 9351	Voltage value of control unit EZS implausible.
Event 9354	Fault in CAN communication with control unit SAM.
Event 9355	Fault in CAN communication with control unit OCP.
Event 9356	Fault in communication on interior CAN databus.

Event 935B Fault in communication with component Multifunction steering wheel.

Filename: F:\Programme\Das\trees\pkw\bedien\mrm5\menues\mnfclistmrm5_001.s

Cell co-ordinate: 5 , 9