

VIN	WDB2110701A123456	Model series/model designation	203.061
Order number		License plate	

Full list of fault codes and events

D000	Control unit TELE AID is defective.
D105	Roadside assistance : No call back from service provider within the defined window of time
D205	MB Info : No call back from service provider within the defined window of time
D600	Line to pushbutton switch Emergency call is interrupted.
D601	Pushbutton switch Emergency call sticks.
D602	Line to pushbutton switch Roadside assistance is interrupted.
D603	Pushbutton switch Roadside assistance sticks.
D604	Line to pushbutton switch MB Info is interrupted.
D605	Pushbutton switch MB Info sticks.
D611	Component GPS antenna is faulty or the lead has open circuit.
D612	Component GPS antenna or the lead has short circuit.
D614	An incompatibility between GPS position and the position determined through the wheel sensors has occurred.
D620	The life signal of control module Airbag cannot be received in time during system start.
D621	The life signal of the airbag control unit cannot be received.
D622	Airbag control module : Crash signal implausible
D630	Component CTEL antenna is faulty or the lead has open circuit.
D631	Component CTEL antenna or the lead has short circuit.
D632	Component TELE AID spare antenna is faulty or the lead has open circuit.
D633	Component TELE AID spare antenna or the lead has short circuit.
D634	CTEL antenna and TELE AID spare antenna are wrongly connected.
D635	Both phone antennas are faulty
D644	CAN bus to control unit OCP (CAN D) : Communication fault with component S93/3 (SOS pushbutton switch)
D662	Control unit TELE AID is defective. : 'CTEL' transmitter and receiver unit
D667	GPS general error > see diagnostic trouble bulletin
D669	Too many CAN messages > see diagnostic trouble bulletin
D670	No connection to component Handsfree system microphone
D672	Handsfree system microphone: short circuit to GND
D681	No connection to component Loudspeaker emergency call
D683	Loudspeaker emergency call: short circuit to GND
D690	CAN signal Vehicle speed faulty (RIZ)
D691	Large deviation determined between wheel speed signal and speed computed based on GPS signal. Wheel speed =0 : GPS=20 km/h
D6D1	TCU software in control module is not programmed. Program control unit.
D6D6	Network access device (NAD) in control module is not programmed. Program control unit.
D6D7	Preferred roaming list (PRL) in control module is not programmed. Program control unit.
D700	The cable to component Additional battery is faulty.

D702	Auxiliary battery has low or high voltage. (<9V ; >16V)
Event D001	 This message does not immediately result in replacement of component. Watchdog error : The control unit has been reset due to an internal error.
Event D010	The supply voltage of the control unit is too low (undervoltage).
Event D011	The supply voltage of the control unit is too high (overvoltage).
Event D102	Roadside assistance : Service provider call is not possible. The telematic does not detect a radio network.
Event D103	Roadside assistance : Service provider call is not possible. The repeat attempts have failed.
Event D104	Roadside assistance : Transmission error during data transfer from the vehicle to the service provider
Event D202	MB Info : Service provider call is not possible. The telematic does not detect a radio network.
Event D203	MB Info : Service provider call is not possible. The repeat attempts have failed.
Event D204	MB Info : Transmission error during data transfer from the vehicle to the service provider
Event D302	Emergency call : Service provider call is not possible. The telematic does not detect a radio network.
Event D303	Emergency call : Service provider call is not possible. The repeat attempts have failed.
Event D304	Emergency call : Transmission error during data transfer from the vehicle to the service provider
Event D402	Stolen vehicle tracking : Service provider call is not possible. The telematic does not detect a radio network.
Event D404	Stolen vehicle tracking : Transmission error during data transfer from the vehicle to the service provider
Event D640	CAN bus to control unit EZS (CAN D) : CAN reception timeout of data of control unit EZS
Event D6B3	Authorization : The service provider's line is busy or you cannot be connected. Retry strategy exhausted.
Event D6B4	Authorization : Telephone network is not available.
Event D6B5	Authorization : Service Center busy. Connection is not possible.
Event D902	Remote door unlocking : Service provider call is not possible. The telematic does not detect a radio network.
Event D903	Remote door unlocking : Service provider call is not possible. The repeat attempts have failed.
Event D904	Remote door unlocking : Transmission error during data transfer from the vehicle to the service provider
Event DA04	Remote door locking : Transmission error during data transfer from the vehicle to the service provider

Filename: F:\Programme\Das\trees\PKW\Tele\LCT\Menues\MnLCT001.S

Cell co-ordinate: 13 , 27