

---

<b>VIN</b>	WDD1714561A001234	<b>Model series/model designation</b>	209.356
<b>Order number</b>		<b>License plate</b>	

---

## Note on fault code 0524

---

The actual values are not okay.

### **Possible cause and remedy :**

- Component B28/9 (Left intake manifold tumble flap position sensor) or component B28/10 (Right intake manifold tumble flap position sensor) is faulty.
- Vacuum supply of component Y22/9 (Intake manifold tumble flap switchover valve) or the aneroid capsule for the tumble flap
- Short or open circuit in position sensor B28/9 (Left intake manifold tumble flap position sensor) or B28/10 (Right intake manifold tumble flap position sensor)
- Actuating lever for left or right tumble flap is worn out or broken.

---

**Filename:** F:\Programme\Das\trees\pkw\motorott\me97\ps\b28\_x.s

**Cell co-ordinate:** 11 , 10