

MODEL 209 as of 1.6.04

Shown on MB Audio 20 radio


- 1 Bolts
A2 Radio



P82.60-4728-11

Modification notes

24.5.06	"Disconnect/connect ground line on battery" removed		
---------	---	--	--

	Remove/install		
1.1	Transfer basic data from radio (A2) to STAR DIAGNOSIS Connect STAR DIAGNOSIS and read out fault memory	When replacing radio (A2). i Installation: transfer temporarily stored basic data to the new radio (A2). STAR DIAGNOSIS diagnosis system	 AD00.00-P-2000-04A *WH58.30-Z-1048-13A
2	Remove upper control panel control unit.		AR54.21-P-1262Q
3	Remove control and operating unit		AR83.40-P-6350QA
4	Remove bolts (1)		
5	Withdraw radio (A2)		
6	Detach coupling from radio (A2)		
7.1	Cover fiber optic cable Notes on fiber optic cable	For telephone "Handy", UPCI system, code 388, For sound system, code 810, For 6-disk CD changer, code 819, For voice control system (VCS [SBS]), code 813 i Install caps on fiber optic cable connector and equipment connector. Model 129, 163, 168, 170, 202, 203, 208, 209, 210, 215, 220, 230, 414, 463.243/244/245/246/247/248/249/ 250/254/309/322/323/332/333	AR82.95-P-0005-01A AH82.70-P-0001-02A
8	Install in the reverse order		

Commercially available tools

Number	Designation	
WH58.30-Z-1048-13A	STAR DIAGNOSIS diagnosis system, Compact Passenger Car	6511 1801 00