

Released fold seam tension cable





When closed the soft top canvas is not pulled at the side under the edge of the rear wall window.




P77.31-2240-01

Operation no. of operation texts or standard texts and flat rates

Category	Op. no.	Operation text
P	025663	Seam on water pocket of soft top canvas; Location:.....Repair
P	025664	REPAIR SEAM ON SOFT TOP CANVAS WATER POCKET, LEFT AND RIGHT

			
Removing			
1	Remove rear window	 Protect body against paint damage	AR67.20-P-5145QA
2	Expose water pocket	 Shown on the left water pocket, if necessary carry out the scope of the work on the right-hand side.	SM77.31-P-0001-02A
3	Glue fold seam to tension cable		SM77.31-P-0002-01A
4	Assemble water pocket		SM77.31-P-0001-02A
			
Install			
5	Install rear window		AR67.20-P-5145QA

Parts ordering notes

Part no.	Designation	Quantity
A 209 778 07 96	Repair kit for water pocket  Water pockets are not required	1
A 002 990 80 97	Rivet (3.2 × 7.9)	As required
A 209 778 01 46	Left retaining bracket	As required
A 209 778 02 46	Right retaining bracket	As required