

<b>VIN</b>	WDB2110701A123456	<b>Model series/model designation</b>	230.475
<b>Order number</b>		<b>License plate</b>	

Full list of fault codes and events

B1013	Circuit KL. 15R has Short circuit.
B1020	Circuit Kl.12VOUT has Short circuit.
B1144	Component N70s7 (Right front reading lamp switch) is defective.
B1148	Component N70s3 (Dome lamp switch) is defective.
B1158	Component N70s6 (Left front reading lamp switch) is defective.
B1644	Communication fault with component B38/2 (Rain/light sensor)
B1645	Internal fault : Rain sensor
B1646	Internal fault : Light sensor
B1883	Component A67e1 (Left reading lamp) has Short circuit or Open circuit.
B1884	Component A67e2 (Right reading lamp) has Short circuit or Open circuit.
B1885 - [0...0]	Component A67m2 (Horizontal adjustment motor) has Open circuit. The fault can be ignored.
B1885 - [1...1]	Component A67m2 (Horizontal adjustment motor) has Short circuit. The fault can be ignored.
B1886 - [0...0]	Component A67m1 (Vertical adjustment motor) has Open circuit. The fault can be ignored.
B1886 - [1...1]	Component A67m1 (Vertical adjustment motor) has Short circuit. The fault can be ignored.
B1887	Motor N70m1 (In-car temperature sensor fan motor) does not run.
B1888	The value of sensor N70b1 (In-car temperature sensor) is implausible.
Event B1010	The supply voltage of the control unit is too low (undervoltage).
Event B1011	The supply voltage of the control unit is too high (overvoltage).

**Filename:** F:\Programme\Das\trees\PKW\BEDIEN\DBE2\Menues\MNDBE201.s  
**Cell co-ordinate:** 7 , 6