

VIN	WDB2110701A123456	Model series/model designation	203.061
Order number		License plate	

Complete list of fault codes

D000	Control unit Sound system is defective.
D004	The control unit was switched off due to excessive temperature (MOST transmitter and receiver unit)..
D010	The supply voltage of the control unit is too low (undervoltage).
D011	The supply voltage of the control unit is too high (overvoltage).
D800	Component H4/27 (Cockpit center speaker (center fill)) is faulty or the lead has open circuit.
D801	Component H4/24 (Right front door speaker, in mirror triangle) is faulty or the lead has open circuit.
D802	Component H4/2 (Right front door speaker) is faulty or the lead has open circuit.
D804	Component H4/23 (Left front door speaker in mirror triangle) is faulty or the lead has open circuit.
D805	Component H4/1 (Left front door speaker) is faulty or the lead has open circuit.
D807	Component H4/29 (Subwoofer) is faulty or the lead has open circuit.
D809	Component Right rear loudspeaker is faulty or the lead has open circuit.
D80B	Component Left rear loudspeaker is faulty or the lead has open circuit.
D80D	Component H4/57 (Right rear surround loudspeaker) is faulty or the lead has open circuit.
D80E	Component H4/54 (Left rear surround loudspeaker) is faulty or the lead has open circuit.
D810	Component B25/6 (Sound amplifier microphone) is faulty or the lead has open circuit.
D811	Component Fan is faulty or the lead has open circuit.

Filename: F:\Programme\Das\trees\PKW\most\snd2\menues\MnSND201.S

Cell co-ordinate: 7 , 16