

VIN	WDB2110701A123456	Model series/model designation	203.061
Order number		License plate	

Full list of fault codes and events

D000	The control unit is faulty.
D001	Watchdog error : The control unit has been reset due to an internal error.
D100	MOST master reports open ring.
D101	MOST component at position 1 reports open ring.
D102	MOST component at position 2 reports open ring.
D103	MOST component at position 3 reports open ring.
D104	MOST component at position 4 reports open ring.
D105	MOST component at position 5 reports open ring.
D106	MOST component at position 6 reports open ring.
D107	MOST component at position 7 reports open ring.
D108 - D10F	MOST component at position 8 - 15 reports open ring.
D116	No MOST data transfer possible, position cannot be located
D117	Specified/actual configuration of MOST ring differs
D135	The wake-up line has Short circuit to ground.
D136	The wake-up line has Short circuit to positive.
D137	Communication on the MOST bus was interrupted during diagnosis.
D140	General CAN bus error
D200	At least one button is sticking or was activated for longer than 120 seconds.
D201	Limit switch is not detected when closing the front flap.
D202	Limit switch is not detected when opening the front flap.
D241	CD/DVD drive : CD or DVD cannot be ejected. If there are no faults or complaints, the fault code can then be disregarded.
D242	CD/DVD drive : Fault in CD/DVD drive
D243	CD / DVD : Error while reading the CD If no customer complaint exists, the fault can be erased.
D250	This control module does not match to the coded model designation.
D251	Component M4/12 (Radio additional fan) is faulty or there is an open circuit in the wiring to the component.
D252	Fault in communication with component Compass module.
Event D004	The control module was switched off due to excess temperature.
Event D011	The supply voltage of the control unit is too high (overvoltage).
Event D145	No or incorrect CAN message from control unit A1 (Instrument cluster)
Event D146	No or incorrect CAN message from control unit N73 (EIS [EZS] control unit)
Event D147	No or incorrect CAN message from control unit N73 (EIS [EZS] control unit)
Event D149	No or incorrect CAN message from control unit N80 (Steering column module)
Event D150	No or incorrect CAN message from control unit A1 (Instrument cluster)
Event D203	Component COMAND or AUDIO has excess temperature.
Event D240	CD/DVD drive : CD/DVD drive is too hot.

Filename: F:\Programme\Das\trees\PKW\Most\Agw\Menues\MnAgw001.s

Cell co-ordinate: 5 , 30