

<b>VIN</b>	WDB2110701A123456	<b>Model series/model designation</b>	203.061
<b>Order number</b>		<b>License plate</b>	

Full list of fault codes and events

912A	The control unit is faulty. ( RAM: read error )
912B	Invalid drive authorization data
912C	The main odometer reading is incorrect (too low).
912E	The control unit is faulty. ( ROM: read error )
912F	Fault when writing the EEPROM
9130	Transmission fault
9132	Sensor 1 for fuel level is jammed.
9134	The brake fluid level is not o.k.
9135	Sensor 2 for fuel level is jammed.
913C	'Reset' pushbutton jamming.
Event 9100	Fault in communication on engine CAN databus.
Event 9101	Fault in CAN communication with control unit N47-5 (ESP, SPS [PML] and BAS control unit).
Event 9102	CAN communication with the engine system is faulty.
Event 9103	Fault in CAN communication with component N15/3 (ETC [EGS] control unit) or ASG Automatic gearshift system.
Event 9104	Fault in CAN communication with control unit N63/1 (DTR control module).
Event 9108	CAN message missing from ESP function 'Tire pressure loss warner'.
Event 9110	Fault in communication on interior CAN databus.
Event 9111	Fault in CAN communication with control unit N73 (EIS [EZS] control unit).
Event 9112	Fault in CAN communication with control unit N10/8 (Rear SAM control module).
Event 9113	Fault in CAN communication with control unit SAM-F.
Event 9114	Fault in CAN communication with control unit RCP Roof control panel. Ignore this fault code if no other complaints exist.
Event 9115	Fault in CAN communication with control unit N22 (AAC [KLA] control and operating unit). Ignore this fault code if no other complaints exist.
Event 9116	Fault in CAN communication with control module A35/8 (TELE AID control unit) or E-call.
Event 9117	Fault in CAN communication with control unit N52 (Soft top control module).
Event 9118	Fault in CAN communication with control unit Upper control panel.
Event 911B	Fault in CAN communication with component N2/10 (Supplemental restraint system control unit) or SRS supplemental restraint system.
Event 911C	Fault in CAN communication with control unit Audio gateway.
Event 911D	Fault in CAN communication with control unit N88 (TPM [RDK] control unit).
Event 9120	Fault in CAN communication with control unit KG.
Event 9121	Fault in CAN communication with control unit AHE trailer recognition.
Event 9122	Fault in CAN communication with control unit N26/9 (Special vehicle multifunction control unit (SVMCU [MSS])).
Event 9127	Fault in CAN communication with control unit TPM Tempomat.
Event 9128	The supply voltage of the control unit is too low (undervoltage).
Event 9133	Control module EZS has detected undervoltage.

---

**Filename:** F:\Programme\Das\trees\PKW\Kombi\kiw2m\menues\mnkiw2m1.s

**Cell co-ordinate:** 5 , 20