

VIN	WDB2110701A123456	Model series/model designation	203.061
Order number		License plate	

Complete list of fault codes

D000	Control unit N87/5 (SDAR control unit) is defective.
D001	Watchdog error : The control unit has been reset due to an internal error.
D004	The control unit was switched off due to excessive temperature (MOST transmitter and receiver unit)..
D011	The supply voltage of the control unit is too high (overvoltage).
D241	The antenna cable from component N87/5 (SDAR control unit) to component A2/82 (SDAR antenna) has an open circuit.
D242	The antenna cable from component N87/5 (SDAR control unit) to component A2/82 (SDAR antenna) has a short circuit.

Filename: F:\Programme\Das\trees\pkw\most\sdar2\menues\MnSDAR21.S

Cell co-ordinate: 3 , 19