
VIN	WDB2110701A123456	Model series/model designation	203.061
Order number		License plate	

Complete list of fault codes

D000	Control unit Voice control is defective.
D001	Watchdog error : The control unit has been reset due to an internal error.
D004	The control unit was switched off due to excessive temperature (MOST transmitter and receiver unit)..
D011	The supply voltage of the control unit is too high (overvoltage).
D500	Microphone 1 has Short circuit to ground.
D501	Microphone 1 has Short circuit to positive.
D502	Discontinuity in line to microphone 1.
D503	Microphone 2 has Short circuit to ground.
D504	Microphone 2 has Short circuit to positive.
D505	Discontinuity in line to microphone 2.

Filename: F:\Programme\Das\trees\PKW\most\sbs2\menues\MnSBS201.S

Cell co-ordinate: 7 , 22