
MODEL 203 as of 24.4.04

## Shown on model 203 with automatic air conditioning, code 581a

1 Bolts

N22 AAC [KLA] control and operating unit



P83.40-2706-04

## **Modification notes**

16.5.06 "Disconnect/connect ground line on battery" removed		
-------------------------------------------------------------	--	--

XX	Remove/install		
1	Remove cover on gearshift lever		AR68.20-P-2310P
2	Remove ashtray from front center console		AR68.20-P-2400P
3	Remove bolts (1)		
4	Remove AC operating and control unit (N22)	<b>i</b> Installation: The AAC [KLA] control and operating unit (N22) must audibly engage.	
5	Install in the reverse order		