








## - Parts list -

Mode :	MD mode	Mod. des. overview :	C SEDAN
FIN/MD :	WDB 2030611E006669	Catalog :	65F
VIN :		Major assembly :	
Sales designation :	C 240	Major assembly MD :	
Assortment class :	Car	Group :	31 - HITCHING MECHANISM
Market :	All	Subgroup :	015 - TRAILER COUPLING

Item no.	Part number	Designation/description	Quantity	Version
70	A 203 899 07 14 7C45	<b>BRACKET</b> TRAILER COUPLING Code: 550+669/550+679  [900] Color footnote	001	
80	A 203 899 06 61 7C45	<b>DASHPOT</b> TOP Code: -669-679-690+550  [901] Color footnote	001	
90	A 203 899 07 61 7C45	<b>DASHPOT</b> BOTTOM Code: -669-679-690+550  [901] Color footnote	001	
120	A 203 310 01 56	<b>BALL HEAD</b> TRAILER COUPLING <b>Replaced by:</b> A 203 310 04 56 Code: 550	001	
120	A 203 310 04 56	<b>BALL HEAD</b> TRAILER COUPLING Code: 550	001	
130	A 000 315 06 29	<b>. CAP</b> BALL HEAD Code: 550	001	
150	N 000000 001081	<b>HEXAGON HEAD BOLT</b> CROSS MEMBER TO SIDE MEMBERS M12X35 Code: 550  [002, 003, 004] To Chassis: A 974999 To Date: 30/06/200...	004	
160	A 203 315 02 80	<b>GASKET</b> AT CROSS MEMBER Code: 550  [005, 006, 007] To Chassis: A 974999 To Date: 30/06/2007	002	
200	A 000 315 15 67	<b>CAP</b> CROSS MEMBER Code: 550	001	
300	A 203 610 11 25	<b>REINFORCEMENT</b> LEFT SIDE MEMBER <b>Replaced by:</b> A 203 610 17 25 Code: -423+550	001	
300	A 203 610 17 25	<b>REINFORCEMENT</b> LEFT SIDE MEMBER Code: -423+550	001	
300	A 203 610 17 25	<b>REINFORCEMENT</b> LEFT SIDE MEMBER Code: 423+550  [008, 009, 010] To Chassis: A 556572 To Date: 30/06/200...	001	
300	A 203 610 21 25	<b>REINFORCEMENT</b> LEFT SIDE MEMBER Code: 423+550  [011, 012, 013] From Chassis: A 449884 From Date: 30/09/...	001	
310	A 203 610 12 25	<b>REINFORCEMENT</b> RIGHT SIDE MEMBER <b>Replaced by:</b> A 203 610 18 25 Code: -423+550	001	
310	A 203 610 18 25	<b>REINFORCEMENT</b>	001	

310	A 203 610 18 25	<b>REINFORCEMENT</b> RIGHT SIDE MEMBER Code: -423+550	001
310	A 203 610 18 25	<b>REINFORCEMENT</b> RIGHT SIDE MEMBER Code: 423+550  [008, 009, 010] To Chassis: A 556572 To Date: 30/06/200...	001
310	A 203 610 22 25	<b>REINFORCEMENT</b> RIGHT SIDE MEMBER Code: 423+550  [011, 012, 013] From Chassis: A 449884 From Date: 30/09...	001
320	N 910104 010001	<b>NUT-AND-WASHER ASSEMBLY</b> REINFORCEMENT TO SIDE MEMBER M10 Code: 550  [014, 003, 004] To Chassis: E 016937 To Date: 30/06/200...	004
325	N 000000 006038	<b>NUT-AND-WASHER ASSEMBLY</b> CROSSMEMBER MOUNTING M8 Code: 550  [005, 006, 007] To Chassis: A 974999 To Date: 30/06/2007	004
330	N 000000 001556	<b>SCREW-AND-WASHER ASSEMBLY</b> REINFORCEMENT TO SIDE MEMBER M10X25 Code: 550  [014, 003, 004] To Chassis: E 016937 To Date: 30/06/200...	004
340	N 000000 001557	<b>SCREW-AND-WASHER ASSEMBLY</b> CROSSMEMBER MOUNTING M10X60 Code: 550  [014, 003, 004] To Chassis: E 016937 To Date: 30/06/200...	002
350	A 203 610 10 25	<b>REINFORCEMENT</b> HITCHING MECHANISM Code: 550  [014, 003, 004] To Chassis: E 016937 To Date: 30/06/200...	001