


MODEL 203.0 /2, 208.3, 210, 215, 220
with CODE (412) Electric tilting/sliding roof
with CODE (414) Glass electric tilting/sliding roof
MODEL 209.3, 211 with CODE (414) Glass electric tilting/sliding roof
MODEL 240 with CODE (414) Glass electric tilting/sliding roof


Shown on model 211



P77.20-2313-06

Modification notes

11.7.02	"Coat slide rails and slide blocks with grease" newly included.	Step 3	
---------	---	--------	--

	Cleaning		
1	Completely open tilting/sliding roof		
2	Clean slide rails and slide blocks (arrows).		
3	Coat slide rails and slide blocks (arrows) thinly with grease		*BR00.45-Z-1046-06A
4	Check tilting/sliding roof for proper function		
5	Close tilting/sliding roof		

Repair materials

Number	Designation	Order number
BR00.45-Z-1046-06A	Klueber Polylub GLY 801 grease	A 001 989 84 51