
VIN	WDB2110751A123456	Model series/model designation License plate	209.365
Order number			

Road test

Test sequence :

- End diagnosis.
- Switch off ignition.
- Start engine.
- Operate switch N72/1s1 (ESP OFF switch).
- Warning lamp A1e41 (ESP warning lamp) comes on.
- Indicator lamp A1e17 (ABS malfunction indicator lamp) comes on.
- Drive vehicle forward at approx. 10 km/h (6 mph).
- After a short distance, start cornering (to the left or right).
- Steering wheel lock greater than 90 degrees
- Drive a quarter of a circle.
- Begin cornering within 10 s.

Specified value :

- Indicator lamp A1e17 (ABS malfunction indicator lamp) goes out.
- Warning lamp A1e41 (ESP warning lamp) goes out.

Fault status :

- Indicator lamp A1e17 (ABS malfunction indicator lamp) has not gone out.
- Warning lamp A1e41 (ESP warning lamp) did not go out.

Possible cause and remedy :

- Read out fault memory of control unit N47-5 (ESP and BAS control module).

Filename: F:\Programme\Das\trees\pkw\Traktion\espmk25\an\AN_fahr.S

Cell co-ordinate: 3 , 9