

<b>VIN</b>	WDB2110701A123456	<b>Model series/model designation License plate</b>	203.061
<b>Order number</b>			

Complete list of fault codes

D000	Control unit CD changer is defective.
D001	Watchdog error : The control unit has been reset due to an internal error.
D004	The control module was switched off due to excess temperature.
D011	The supply voltage of the control unit is too high (overvoltage).
D706	The CD changer signals excess temperature.
D707	Error while reading the CD
D710	CD store fault : CD magazine is not ejected.

**Filename:** F:\Programme\Das\trees\PKW\most\cdc2\menues\MnCDC201.S  
**Cell co-ordinate:** 7 , 15