Diagnosis Assistance System

VIN	WDB2110701A123456	Model series/model designation	203.061
Order number		License plate	

Complete list of fault codes

D000	D000 - [01] The component is faulty.		
D000	- [3255] The component is faulty.		
D010	The supply voltage of the control unit is too low (undervoltage).		
D240	CD/DVD drive : CD/DVD drive is too hot.		
D241	CD/DVD drive : CD or DVD cannot be ejected.		
D242	CD/DVD drive : General read error		
D243	CD/DVD drive : The CD/DVD drive is too cold.		
D302	The cable to the GPS antenna has a short circuit.		
D303	The cable to the GPS antenna has an open circuit.		

Filename:F:\Programme\Das\trees\PKW\most\navi2\menues\Mnnavi01.SCell co-ordinate:5, 16