

01/2011 [2010-12-09] - AddOns:;1709;1711;1715;1 Ignition ON 704;1708;1707;1713;1717 VIN : WDD1714561A001234 Battery voltage: 12.5 V


Vehicle 209.372 Control unit ME 9.7

Intake camshaft of left cylinder bank

Figure legend/figure :
- Camshaft adjuster

Test sequence :
- Remove cylinder head cover and check whether the interference fit between drive sprocket and sprocket on camshaft adjuster 'Left intake' has twisted (laser markings 1 and 2 must be positioned over each other).

Question :
- Is the camshaft adjuster OK?



ESC F1 YES NO F3 F4 F6 F8 F11