



VIN	WDB2110701A123456	Model series/model designation License plate	203.061
Order number			

Full list of fault codes and events

B1000	Control unit N73 (EIS [EVS] control unit) is defective.
B1003	Communication fault with control unit N26/5 (Electric steering lock control module)
B1004	Control unit N26/5 (Electric steering lock control module) is defective.
B1005	Communication fault with control unit N26/5 (Electric steering lock control module)
B100C	Output 'Circuit 15' :  +
B100D	Output 'Circuit 50' :  +
Event B1001	Undervoltage supply
Event B1002	Overvoltage supply
Event B1006	Central locking : Play protection is active.
Event B1007	Interior CAN bus : Open circuit in wiring / CAN bus in single-wire mode
Event B1008	Interior CAN bus : Short circuit
Event B1009	Communication through the interior CAN bus is faulty.

Filename: F:\Programme\Das\trees\PKW\Fahrber\EVS4\Menues\MNEVS401.s

Cell co-ordinate: 7 , 27