

VIN	WDB2110701A123456	Model series/model designation	209.375
Order number		License plate	

Test signal cable of component B48 (Front passenger seat occupied and child seat recognition) for $\Gamma \neg \Gamma +$.

Test prerequisites :

- Relevant fault codes exist or a complaint has been received.

Status of the relevant fault codes:

Current fault code 'B106E The component or the signal line to the component B48 (Front passenger seat occupied and child seat recognition) has $\neg // -$ or $\Gamma \neg \Gamma +$.' not present

Current fault code 'B106C Fault in communication with component B48 (Front passenger seat occupied and child seat recognition) or there is a cable fault.' not present

Test sequence :

- Switch off ignition.
- Detach coupling at component B48 (Front passenger seat occupied and child seat recognition).
- $\perp \leftarrow \textcircled{\Omega} \rightarrow \perp$ 3 (B48)

Specified values :

- Resistor $< 1 \Omega$

Question :

- Is the measurement value OK?

Filename: F:\Programme\Das\trees\PKW\SRS\ABZK\PS\PSCB48b.S

Cell co-ordinate: 3 , 8